

Ameesha A'

Inspection report of the parks and status of playing equipments

Date: - 01.06.2015 to 15.06.2015

Inspection on 15.06.2015

S. No.	Name of Park and location	Playing Equipments										Condition of park	Repair	Painting	Remarks			
		Swing	Jungle Jim	Slide	Seesaw	Bridge Ladder	Parallel	Revolving	Mini House	Benches	Umbrella							
1	Abul Fazal Road Park	-	2	1	-	1	-	-	-	-	-	-	11	1	OK	N	N	
2	Asia House KG Marg	1	-	2	1	-	1	1	-	-	-	-	8	-	OK	N	N	
3	Bapa Nagar	-	-	-	-	-	-	-	-	-	-	-	2	-	OK	N	N	Benches Painting park completed
	Park Near C-1/11	-	-	-	-	-	-	-	-	-	-	-	-	-	OK	N	N	
	Park Near C-1/21	-	-	-	-	-	-	-	-	-	-	-	-	-	OK	N	N	
	Park Near C-1/49	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near C-1/66	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near C-1/73	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near C-1/41	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near C-1/47	-	-	-	-	-	-	-	-	-	-	-	-	-				
4	CPWD Colony Hanuman Road	-	-	-	-	-	-	-	-	-	-	-	-	-				
	(a)	2	-	-	-	-	-	-	-	-	-	-	-	-				
	(b)	3	-	2	1	1	-	-	-	-	-	-	16	-	OK	N	N	Painting park completed
	(c)	-	-	-	-	-	-	-	-	-	-	-	-	-				
	(d)	-	-	-	-	-	-	-	-	-	-	-	-	-				
5	Hailey Lane Dhobi Ghat Park	-	-	-	-	-	-	-	-	-	-	-	-	-				
6	Hailey Lane Park	1	-	1	1	-	-	1	-	-	-	-	-	-				
7	Hanuman Road	2	1	-	2	-	-	-	-	-	-	-	11	-	OK	N	N	Benches & Painting park completed
8	Kaka Nagar	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near D-1/19	1	-	1	1	1	-	-	-	-	-	-	4	-	OK	N	N	
	Park Near D-1/60	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near D-1/60	-	-	-	-	-	-	-	-	-	-	-	4	-	OK	N	N	

S. No.	Name of Park and location	Playing Equipments										Condition of park	Repair	Painting	Remarks			
		Swing	Jungle Jim	Slide	Seesaw	Bridge Ladder	Parallel	Revolving	Mini House	Benches	Umbrella							
	Park Near D-II/ 63	-	-	-	-	-	-	-	-	-	-	-	2	-	OK	N	N	Repaired and Painting park completed
	Park Near D-II/ 66	-	-	-	-	-	-	-	-	-	-	-	2	-	OK	N	N	
	Park Near D-II/ 69	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near D-II/ 147	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near D-II/ 157	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near D-II/ 164	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near D-II/ 184	-	-	-	-	-	-	-	-	-	-	-	2	-	OK	N	N	
	Park Near D-II/ 186	-	-	-	-	-	-	-	-	-	-	-	2	-	OK	N	N	
	Park Near D-II/ 203	-	-	-	-	-	-	-	-	-	-	-	-	-				
9	M.S. Apartment KG Marg	1	-	1	1	-	1	-	-	-	-	-	3	-	OK	N	N	Painting park completed
10	Municipal Market Park	2	1	1	3	1	1	-	-	-	-	-	7	-	OK	N	N	Painting park completed
11	Pandara Park	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near C-I/ 23	-	3	1	-	-	-	-	-	-	-	-	4	-	OK	N	N	Benches Painting park completed
	Park Near D-II/ 15	-	-	-	-	-	-	-	-	-	-	-	2	-	OK	N	N	
	Park Near School	4	-	-	-	1	-	-	-	-	-	-	3	-	OK	N	N	Painting park completed
12	R.P. Road near Jawahar Bhawan	-	-	-	-	-	-	-	-	-	-	-	-	-	OK	N	N	
13	Tiلاك lane	-	-	-	-	-	-	-	-	-	-	-	-	-				
	Park Near in front of School	-	-	-	-	-	-	-	-	-	-	-	6	-	OK	N	N	
	Tikona Park	-	-	-	-	-	-	-	-	-	-	-	-	-				
14	Tiلاك Statue at Tiلاك Marg W-Point	-	-	-	-	-	-	-	-	-	-	-	-	-				
15	Todamal Road Behind Babar Place Park	1	-	1	1	-	1	1	-	-	-	-	-	-	OK	N	N	Gril & Painting park completed
16	Todamal Road Park	3	1	2	1	-	1	-	1	1	-	1	9	-	OK	N	N	
17	Todamal Square park	2	-	2	2	-	2	-	1	-	-	2	2	-	OK	N	N	Repaired and Painting park completed
18	Triangular Park- Near Dustbin	1	-	1	1	-	1	-	-	-	-	1	1	-	OK	N	N	

S. No.	Name of Park and location	Playing Equipments										Condition of park	Repair	Painting	Remarks	
		Swing	Jungle Jim	Slide	Seesaw	Bridge Ladder	Parallel	Revolvin 9	Mini House	Benches	Umbrella					
19	Triangular Park Tordamal Road Near P/office	1	-	1	1	-	1	-	-	1	-	1	OK	N	N	
20	Vakil Lane I Park	-	-	-	-	-	1	-	-	0	-	0	OK	N	N	
21	Vakil Lane II Park	1	-	1	1	-	0	1	-	0	-	0	OK	N	N	Painting park completed
	Total	26	8	18	17	4	5	6	1	104	1					

EE(R-I)

AE-II(R-I)

JE(R-I)

Inspection report of children park and status of playing equipments

Date: - 01.06.2015 to 15.06.2015

Inspection on: - 14.06.15

S. No.	Name of Park and location	Playing Equipments										Condition of the park	Repair	Painting	Remarks
		ABCD Ring	Roller Slide	Four seater round	Standing rounder	Spring pillar	Two seater up & down round Jhula	Two seater ballance Jhula	Four seater ballance Jhula	Bridge Jhula	Duck Jhula				
1	Children Park (India Gate)	2	2	1	1	2	3	3	3	2	3	OK	N	N	Repaired & Duck Jhula Painting completed
Total		2	2	1	1	2	3	3	3	2	3	OK	N	N	
		Playing Equipments													
S. No.	Name of Park and location	Bucket slider	Little MPPS	Micky Mouse Double swim	MPPS	Double swing	Micky Mouse Jhula	Child Jhula	Bucket swing	Round slider	Swim slider	Condition of the park	Repair	Painting	Remarks
1	Children Park (India Gate)	1	1	1	2	2	1	1	1	1	2	OK	1 no.	N	MPPS painting completed
Total		1	1	1	2	2	1	1	1	1	2	OK	N	N	
		Playing Equipments													
S. No.	Name of Park and location	Micky Mouse Walker	Air Walker	Ab Crunch (Double)	Air Swing	The Horse	Glider (Leg Press)	Seated Chest Press	Push n Pull up Chair	Parallel Bar	Poles With Fixed Weight	Condition of the park	Repair	Painting	Remarks
1	Children Park (India Gate)	1	1	1	1	1	1	1	1	1	1	OK	N	N	Benches & Painting park completed
Total		1	1	1	1	1	1	1	1	1	1	OK	N	N	
		Playing Equipments													
S. No.	Name of Park and location	Cross Walker	Star Stepper	Cross Stepper (Elliptical)								Condition of the park	Repair	Painting	Remarks
1	Children Park (India Gate)	1	1	1								OK	N	1 no.	Fountain Water clean & painting completed
Total		1	1	1								OK	N	N	